

In any correspondence relating to this report please quote:

District L027

Policy

EMM1026222

Item No. L11

User Ref 111

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting Equipment Regulations 1998

(Regulation 9)

Employer (and/or plant

THE EXPANDED PILING COMPANY LIMITED

Address

THE EXPANDED PILING CO LTD CHEAPSIDE WORKS WALTHAM GRIMSBY LINCOLNSHIRE DN37 0JD

For the attention of:

MR. S. BARRETT

Address at which the examination was made

As above

Description of Lifting Equipment

DIESEL HYDRAULIC CONTINUOUS FLIGHT AUGER BORED PILE DRILLING MACHINE

Distinguishing Number

CB9

Makers Name

RAWCO

None

Year of Manufacture

Not applicable

Safe Working Load

20 ton extraction winch. 1 ton service winch.

Nature of Examination

Thorough examination, within an interval of twelve months, unless otherwise indicated

Identification of any part found to have a defect which is or could become a danger to persons. State description of the defect, and any repair, renewal or alteration

required to remedy the defect, either immediately or within a specified time.

Other defects and remedies.

A number of track fixing bolts are loose and should be secured. The service line safe working load should be clearly marked.



13

vers 29 ID: 8643283